

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

1	Name of the officer	Sathyanarayana M K Assistant Engineer, Balal GP
2	Name of the school	Mother Teresa Residential School Parappa
3	Classification building	RCC 6.20 x 6.20 x 3.6 (T No's)
4	Period for which the Certificate issued	2026-2027
5	Nature of defects if any	
	a) Foundation and basement	No
	b) Superstructure	No
	c) Doors and windows	No
	d) Wood work wrought and put up	No
	e) Roof	No
	f) Flooring	No
	g) Miscellaneous	No
6	Any major defects noticed which will render the building unsafe in any manner	No
7	Whether maintenance works have been done properly	No
8	Whether the structure is sound or not for	The structure appears generally sound for conducting classes based on visual inspection at the time of inspection.

NOTE: 1. Stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to floor etc

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the School was inspected by me on 29/05/2026 and found to be fit to conduct classes for the period 2026-27 for the reasons stated above.

Place Balal
Date 29-05-2026



Signature and Designation
ASSISTANT ENGINEER
LOCAL BODY GOVERNMENT
BALAL GRAMA PANCHAYAT